



The  
**Professional's Choice**  
for  
**Environmental Testing**

1675 N. Commerce Parkway, Weston, FL 33326  
Tel: (954) 384-4446 Fax: (954) 384-4838

## Certificate of TEM Analysis

---

Prepared For: H&G HOME INSPECTION SVS  
BRAMPTON, ON L6Z 1K6

Phone 647-448-2099  
Email: Gabriellee58@gmail.com

Test Address: 95 HABITANT DR  
NORTH YORK, ON M9M 2P4

Sample Number: 814111-1-2  
PRO-LAB COC#: 814111

Collection Location: INSIDE FURNACE ROOM (1), INSIDE BASEMENT LR (2)

Date Collected: JANUARY 01,2014  
Receive Date: JANUARY 02,2014  
Analysis Date: JANUARY 06,2014  
Report Date: JANUARY 07,2014

### **Asbestos Results: NO STRUCTURES DETECTED**

(see attached datasheet for details)

Erika Piechowski, Technical Manager

Carlo Ochoa, Quality Control Manager

---

Samples analyzed by this test method are subject to the inherent limitations of TEM. This report shall not be reproduced, except in full, without written permission from PRO-LAB/SSPTM, Inc. Analysis performed by AmeriSci (NY ELAP #10984).

All tests are subject to false positives and false negatives and the analyses and interpretation(s) made herein may not be regarded as a basis for taking any action regarding health or remediation of the tested materials.

**For more information please contact PRO-LAB at 954-384-4446**

---

Client Name: Environmental Hazards Services, Inc.

**Table I**  
**Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)**  
 10-3788; 814111-1; 814111-2

AmeriSci Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns)			Structure Density (struc/sq mm)		Structure Concentration (struc/cc air)		Type of Asbestos
						0.5-5.0	>=5.0	Total	>=5.0	Total	>=5.0	Total	
01 Location:	814111-1		300	.100	0.0128	0.0	0.0	0.0	<10	<10	<0.0128	<0.0128	NSD
02 Location:	814111-2		300	.100	0.0128	0.0	0.0	0.0	<10	<10	<0.0128	<0.0128	NSD

\* concentration represented by the detection of 1 structure

\*\* not analyzed

NSD: No Asbestos Structures Detected

Reviewed By: \_\_\_\_\_

Analyzed By: \_\_\_\_\_

Date: 1/7/2015

Beverly A. Schrage